



The DNA of tech.™

Product Termination Notification

Product Group: AC/Tue Jan 24, 2023/PTN-AC-00501-2023-REV-0



Vishay BCcomponents Aluminum Capacitors Discontinuance of Radial 85°C Series for India market

For further information, please contact your regional Vishay office.

CONTACT INFORMATION

Americas

Walter Bonomo
Vishay Americas
One Greenwich Place
Shelton United States 06484
Phone: +1 704 924 5188
Fax: +43 463 3834 301
Walter.Bonomo@Vishay.com

Europe

Gerald Tatschl
Vishay BCcomponents Austria GmbH
Ebentaler Straße 140
Klagenfurt Austria 9020
Phone: +43 463 3834 314
Fax: +43 463 3834 301
Gerald.Tatschl@Vishay.com

Asia

Boon Hooi Tan
Vishay Intertechnology Asia Pte. Ltd.
37A Tampines Street 92 #07-01
Singapore Singapore 528886
Phone: +65 6780 7759
Fax: +43 463 3834 301
BoonHooi.Tan@Vishay.com

Description of Change: Termination of Vishay BCcomponents series 097 RLP India (MAL5797, MAL5297) series.

Any PN within these series, whether listed or not, will also be affected.

Classification of Change: Poor availability of key raw materials and low market demand.

Expected Influence on Quality/Reliability/Performance: N/A

Part Numbers/Series/Families Affected: MAL579715101E3, MAL579726101E3, MAL579791228E3, MAL529715109E3, MAL529791228E3

Vishay Brand(S): Vishay BCcomponents

Time Schedule:

Last Time Buy Date: Fri Mar 31, 2023

Last Time Ship Date: Thu Nov 30, 2023

Sample Availability: N/A

Product Identification: Series names, capacitance and voltage values are printed on the products, part numbers are shown on packaging labels.

Qualification Data: N/A

This PTN is considered approved, without further notification, unless we receive specific customer concerns before Thu Feb 23, 2023 or as specified by contract.

Issued By: Alexander Wolf, alexander.wolf@vishay.com



Replacement Table
PTN-AC-00501-2023-REV-0

Page: 1 of 1

Part Number	Description		Part Number Crossing*	Description Crossing	Remarks
MAL579715101E3	100uF 16V 6.3x7 85°C 2000h (SA)	→	MAL514290022E3	100uF 16V 6.3x7 105°C 1000h (SA)	
MAL579726101E3	100uF 25V 6.3x7 85°C 2000h (SA)	→	MAL514290023E3	100uF 25V 6.3x7 105°C 1000h (SA)	
MAL579791228E3	2.2uF±10% 50V 4x7 85°C 2000h (SA)	→	MAL514290024E3	2.2uF±10% 50V 4x7 105°C 1000h (SA)	

* Replacement series 142 RHS INDIA - MAL5